

Annexure D

BUILDING SAFETY CERTIFICATE

No. 42

Dated: 21.03.2025

It is certified that the existing building **Score Well International school** at Vill.- Khamhaul Pargana – Paila Tehsil- Lakhimpur Distt.-Lakhimpur- Kheri (UP) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|-------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | Ground + 01 | NA | NA | NA | NA | NA |


The building is owned/occupied by **Score Well International school** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Rural Engineering Department** on **07.03.2025** in the presence of **Mr. Satya Narayan Verma Vill.- Khamhaul Pargana – Paila Tehsil- Lakhimpur Distt.-Lakhimpur- Kheri (UP)** and that the building/premises is fit for occupancy for running school with effect from **07.02.2025** for a period of **Five Years** in accordance with rule and subject to compliance of the specific conditions as appended.

- 1- If intensity of earthquake in this region occurs more than 06.00 on reactor scale this certificate become invalid, inspection of building should be done again.
- 2- If No's of floor is increased then this certificate become invalid.

Issued on 21.03.2025 at Lakhimpur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :





रवि शंकर श्रीवास्तव
सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग
प्रखण्ड-लखीमपुर-खीरी

Name :

Designation :

Name & Address of Department/ Office: _____


PRINCIPAL
Score Well
International School
Gola Gokarannath (Kheri)

For SCORE WELL INTERNATIONAL SCHOOL

Manager/Treasurer